



Land Subsidence Rate in the Fort Grant Rd and Willcox Areas, Cochise and Graham Counties
Based on Radarsat-2 Satellite Interferometric Synthetic Aperture Radar (InSAR) Data
Time Period of Analysis: 1.0 Years 04/12/2019 To 04/30/2020

© MDA 2019 - 2020

Explanation

04/12/2019 To 04/30/2020

Land Subsidence Rate

	Decorrelation/No Data
	Greater 7 cm/yr (2.8 in/yr)
	5 - 7 cm/yr (2.0 - 2.8 in/yr)
	3 - 5 cm/yr (1.2 - 2.0 in/yr)
	2 - 3 cm/yr (0.8 - 1.2 in/yr)
	1 - 2 cm/yr (0.4 - 0.8 in/yr)
	0.5 - 1 cm/yr (0.2 - 0.4 in/yr)
	0 - 0.5 cm/yr (0 - 0.2 in/yr)

Subsidence Feature

Hardrock

Earth Fissures

Highways and Interstates

Interstate

US

State

Roads

Railway

1:220,000



Decorrelation (white areas) are areas where the phase of the received satellite signal changed between satellite passes, causing the data to be unusable. This occurs in areas where the land surface has been disturbed (i.e. bodies of water, snow, agriculture areas, areas of development, etc).

Earth fissures were mapped by the Arizona Geological Survey.
For information on earth fissures visit: www.azgs.gov/EFC

Coordinate System: NAD 1983 UTM Zone 12N
Projection: Transverse Mercator
Datum: North American 1983
Units: Meter
Created: 5/21/2020

